

List of Figures

Figures	Page
1A: A N.C. Division of Forest Resources' Water Quality Forester inspects a completed and stabilized harvest site.....	19
3A: Example of a detailed, hand-drawn preharvest plan map.....	35
3B: Excerpt from the USGS "Rougemont" 7.5-minute quad topo map.....	37
3C: Excerpt from NRCS soil survey map of the same location as shown in Figure 3B.....	38
3D: Aerial photo of same Durham County location as shown in Figures 3B and 3C.....	39
4A: Diagram showing SMZ continuing and wrapping around the head of a stream channel.....	44
4B: SMZ corridors on a timber harvest in Burke County, N.C.....	44
4C: Broadside view of SMZ in the central piedmont of North Carolina.....	45
4D: SMZ on a timber harvest in Orange County, N.C.....	46
4E: A forest road constructed through a SMZ.....	46
4F: Stabilized roadside ditch crossing in Bertie County, N.C.....	48
4G: Ephemeral area protected during logging.....	49
5A: Cross-section view of a broad-based dip and outlet.....	52
5B: Waterbar constructed across a skid trail in Wilkes County, N.C.....	54
5C: View of the trench along the uphill face of the waterbar.....	54
5D: A waterbar 'tied-in' to the adjoining side / cut bank.....	55
5E: A turnout used together with a waterbar on a skid trail.....	56
5F: A turnout used as a 'wing ditch' alongside a forest access road in Henderson County, N.C.....	56
5G: A forest road with an inside ditchline in Ashe County, N.C.....	57
5H: View of the outlet end of a cross-drain installed underneath a permanent forest road in Wilkes County, N.C.....	59
5I: Schematic cross-sectional sketch of crowned, insloped, and outsloped road surface profiles.....	60
5J: Temporary sediment capture alongside a forest road.....	61
5K: A functioning sediment pit excavated alongside a forest road.....	63
5L: Sketch of properly installed silt fence.....	64
5M: Sketch of bales used to capture sediment.....	65
5N: A brush barrier alongside a closed road in Caldwell County, N.C.....	66
5O: A brush barrier at the base of an active road.....	66
5P: Check dams installed within a turnout from a forest road.....	67
5Q: A permanent stream crossing on a forest road.....	69
5R: Schematic drawing of proper bridgemat installation.....	70
5S: Side view of a wooden bridgemat skid trail crossing.....	70
5T: Steel bridgemat installed for a skid trail stream crossing.....	71
5U: Schematic views of proper culvert installation.....	73
5V: Sketch of a stream channel cross-section for determining temporary culvert size.....	74
5W: Culvert installed on a forest road in Montgomery County, N.C.....	75
5X: Cross-section sketch of a ford crossing.....	76
5Y: A ford crossing in Henderson County, N.C.....	77
5Z: A pole crossing installed within a dry ditch for temporary log road access in northeastern North Carolina.....	78
5AA: A forest road with broad-based dip.....	81
5BB: A forest road and stream crossing.....	82
5CC: A permanent forest access road in Montgomery County, N.C.....	82
5DD: A public road entrance from a forest road.....	83
5EE: A skid trail and stream crossing in Durham County, N.C.....	84
5FF: A curving skid trail in western North Carolina.....	85
5GG: Active logging deck.....	87
6A: Example diagram of block layout for ditches.....	113
7A: Applying herbicides with tractor-mounted equipment in eastern North Carolina.....	115
8A: A trailer used for holding fluid containers on a logging job.....	119
9A: Pulling a fireplow in Bladen County, N.C.....	123
10A: Ground-level view of a freshly pulled bed in eastern North Carolina.....	128
11A: Skid trail with logging debris packed down on the trail.....	133
11B: A stream crossing that needs rehabilitation work.....	134
11C: Same stream crossing after rehab work is completed.....	134
11D: Erosion control mat installed for groundcover.....	136